SPECIFICATION

XEAST

XEAST XE-A[illegible] [illegible]

[illegible]	XEAST XE-A[illegible]
[illegible]	XEAST[illegible]XE-P[illegible]
[illegible]	XE-40A[illegible]XE-60A[illegible]XE-80A[illegible]XE-100A[illegible]XE-120A
[illegible]	0.05[illegible]40m[illegible]60m[illegible]80m[illegible]100m[illegible]120m[illegible]
[illegible]	±1.5mm[illegible]±0.06in[illegible]
[illegible]	m / in / ft
[illegible]	20[illegible]
[illegible]	[illegible]0-180°[illegible]
[illegible]	[illegible]/[illegible]/[illegible]
[illegible]	[illegible]30[illegible] 30[illegible]
[illegible]	[illegible]635nm[illegible]<1mW[illegible]II
[illegible]	[illegible]& IP54[illegible]
[illegible]	[illegible]USB[illegible]USB[illegible]4[illegible]2[illegible]
[illegible]	[illegible]4000[illegible]
[illegible]	0[illegible]40°C[illegible]32[illegible]104°F[illegible]
[illegible]	-10[illegible]50°C[illegible]14[illegible]122°F[illegible]
[illegible]	1 *[illegible] 1 * USB[illegible] 1 *[illegible] 1 *[illegible] 1 *[illegible]

PRODUCT PICTURES

XEAST

[illegible] [illegible] XE-A[illegible]

XEAST
XE-100A
Laser Distance Meter
0.05m
100m
MEAS
UNIT
CLR
OFF

CAUTION
LASER RADIATON
DO NOT STARE INTO BEAM
CLASS II(2)LASER PRODUCT
OUTPUT:<1mW
WAVELENGTH:λ =635nm
Carefully read the user manual
before use to ensure safety
2*AAA 1.5V
Batteries
QC
PASSED

XE-100A
XEAST

Laser Distance Meter
MEAS
UNIT
CLR
OFF

● APPLICATIONS

XEAST®

□□□□□□□□□□□□□□ □□□□□□□ 40m 60m 80m 100m 120M

Precise and Efficient
Wide measuring range & Accuracy is ±2mm
XBRST
XE-100A

Distance Measurement

Volume Measurement

Indirect Measurement -Pythagorean Theorem

Portable Handheld Digital Laser Distance Meter

Area Measurement

Continuous Measurement

● TERMS OF TRADE

□□□□□□□

1□□□□□□

□□□T / T□L / C□Paypal□MoneyGram□□□□□□□□□□□□□□□□□□□□□□

□□□□30□□□□□□□□□□□□70□□□□□

2□□□□□□

□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□oftern□Express□DHL□TNT□UPS□□□□□□□EMS□SPSR□139 Express□□□□LCL□FCL

□□□

● COMPANY INFORMATIONS

SALES TEAM
YEAST®
Your Testing Partner
WOKRSHOP