

XEAST 2019 光强度计 Lux Meter 光强度计 XE-912

● SPECIFICATION

XEAST®

光强度计是一种用于测量光强度的仪器。它广泛应用于照明工程、摄影、农业、工业等领域。XEAST 2019 光强度计 XE-912 是一款高精度、高稳定性的光强度计，具有多种测量模式和单位选择功能。其测量范围宽，精度高，响应速度快，是光强度测量的理想选择。

显示屏	单色 LCD 屏 4 位
测量范围	0 Lux ~ 200K Lux, 0Fc ~ 20KFc
分辨率	& Lt 1000: 0.1; & gt; 1000: 1
光谱响应	CIE photopic (CIE 标准观察者)
显示模式	LCD "-OL-" 表示 "-LO-"
色度响应	CIE Vλ (f1 ' ± 6%, f2' ± 2%)
精度	± 3% rdg ± 8 d (& lt; 10,000Lux), ± 4% rdg ± 10d (& gt; 10,000Lux)
响应时间	500ms
电源	3 * 1.5V "AAA" 电池
功耗	60 mW
工作温度 / 湿度	工作温度: -20 ~ 60 °C, -4 °F ~ 140 °F; Humidity: 10% ~ 90RH%
存储温度 / 湿度	存储温度: -20 ~ 60 °C, -4 °F ~ 140 °F; Humidity: 10% ~ 75RH%
尺寸 (L * W * H)	174.5 * 56 * 30.5mm
重量	84g

● PRODUCT PICTURES

XEAST®









Meter Description


- ① Photo detector
- ② LCD display
- ③ Hold button
- ④ Power ON/OFF button
- ⑤ MAX/MIN button
- ⑥ Fc/Lux button
- ⑥ Battery compartment
- ⑦ Battery Cover
- ⑧ Nameplate



LCD Display Description

- ① Hold icon
- ② Auto power off Icon
- ③ Temperature readings
- ④ Light readings
- ⑤ Illuminance units Icon
- ⑥ Temperature unit Icon
- ⑦ Low battery indication
- ⑧ MAX/MIN icon







SALES TEAM



WOKRSHOP

