

XEAST 2019 Lux Meter XE-912

● SPECIFICATION



XX

Display	4-Digit LCD
Measurement Range	0 Lux ~ 200K Lux (0Fc ~ 20KFc)
Resolution	< 1000: 0.1; >= 1000: 1
Color Temperature	CIE 1931 CIE Illuminant
Display	LCD "-OL-" "-LO-"
Accuracy	CIE λ_{eff} $f_1' \leq 6$ $f_2' \leq 2$
Accuracy	$\pm 3\% \text{rdg} \pm 8d < 10,000 \text{Lux}$ $\pm 4\% \text{rdg} \pm 10d > 10,000 \text{Lux}$
Response Time	500ms
Power Consumption	XXXXXXXXXXXXXXXXXXXXXXXXXXXX
Operating Time	60min
Operating Temp/ Humidity	XXXXXXXXXXXXXXXXXXXXXXXXXXXX 15XXXXXXXXXXXXXXXXXXXX
Storage Temp/ Humidity	-20 ~ 60°C / -4°F ~ 140°F; Humidity 10 ~ 90RH
Storage Temp/ Humidity	-20 ~ 60°C / -4°F ~ 140°F; Humidity 10 ~ 75RH
Battery	3 * 1.5V "AAA"
Dimensions (L * W * H)	174.5 * 56 * 30.5mm
Weight	84g

● PRODUCT PICTURES










Meter Description



- ① Photo detector
- ② LCD display
- ③ Hold button
- ④ Power ON/OFF button
- ⑤ MAX/MIN button
- ⑥ Fc/Lux button
- ⑥ Battery compartment
- ⑦ Battery Cover
- ⑧ Nameplate



LCD Display Description

- ① Hold icon
- ② Auto power off Icon
- ③ Temperature readings
- ④ Light readings
- ⑤ Illuminance units Icon
- ⑥ Temperature unit Icon
- ⑦ Low battery indication
- ⑧ MAX/MIN icon







SALES TEAM



WOKRSHOP

