

□□	□□□ □□ □□, □□□ □□ □□ □□
□□ □□	KPA, INHg, KgF / cm2, PSI, Bar
□□ □□□	Torr, mmHg, □□□□, %
□□ □□ □□	1.5V AA □□□ X 4 = 6V
□□ □□	□□□ □□
□□ □□	°F, °C
□□	0 ~ 6 Mpa
□□□	0 ~ 4 Mpa
□□□	1Kpa
□□ □□□	± 0.5 %
□□□ □□	100Bar, 10Mpa
□□	-20 °C ~ +60 °C
□□□ □□	30 □□ □□
□□ □□ □□	-50 °C -150 °C (-58 °F -302 °F)
□□ □□ □□□	& lt; 50 °C (+/- 0.1 °C) & gt; 50-100 °C (+/- 0.2 °C), & gt; 100 °C (+ / 1 °C)







数显表阀

WK-6889







● TERMS OF TRADE

XEAST®

1). 付款条件：电汇 T / T, L / C, Paypal, MoneyGram 或 Western Union 均可。

订金 30 % 发货前 70 % 付清。

2). 运输条件：

我们提供多种运输方式供您选择。我们提供空运 (DHL, TNT, UPS, 联邦快递, EMS, SPSR, 139 快递等), LCL, FCL

3). 我们提供多种付款方式，包括电汇、支票、信用卡、支付宝、微信支付等。

● COMPANY INFORMATIONS

XEAST®



SALES TEAM



WOKRSHOP

